

To: [Nonresponsive based on revised scope]@tetrattech.com]
Cc: [Nonresponsive based on revised scope]@tetrattech.com[Nonresponsive based on revised scope]@tetrattech.com]; [Nonresponsive based on revised scope]@tetrattech.com[Nonresponsive based on revised scope]@tetrattech.com];
[Nonresponsive based on revised scope]@tetrattech.com]
From: Wagner, Christine[/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=12068C1889924ECF96F692831F0C77D4-CWAGNE02]
Sent: Thur 8/20/2020 7:23:51 PM (UTC)
Subject: And 1 more item
[Conex Survey 190820.pdf](#)

[Nonresponsive based on revised scope]

Here is an example of the conex box surveys performed as part of our radiation work plan. These are shared with unified command. It is important that the conex does not meet the next level of radiation protection (rad rope) as defined in 10 CFR. I believe the max is 10 mR/hr, but I'm a little fuzzy. This would be an HP question

Thanks
Chris